



1

COUNTER MOUNTING PATTERN




SCREW BOTTOM PLATE TO THE COUNTER
USING #14 X 1 1/2" PHILLIPS PAN HEAD
SHEET METAL SCREWS (PROVIDED)




2

ROUTE CHARGING CABLE
THROUGH THE STAND AS SHOWN




3



ROUTE CHARGING CABLE
THROUGH ENCLOSURE
OR VESA MOUNT.
INSTALL ON STAND USING
M4 X 8mm PHILLIPS
PAN HEAD SCREWS
(PROVIDED)


4

ATTACH CHARGING CABLE TO THE TABLET, LEAVE A SMALL LOOP OF CABLE BENEATH THE TABLET





5

INSTALL THE ENCLOSURE TOP PLATE/VESA MOUNT PER THEIR INSTRUCTIONS




Tilt Tension Adjustments



ADJUST HINGE TENSION USING WRENCH (PROVIDED)

IN THE BOX




T30 TORX L-Wrench



M4 X 8mm
Phillips Pan Head Screws



#14 X 1 1/2"
Phillips Pan Head Sheet Metal Screws




Rise Pole Stand

PowerMove Connector

Assembly Instructions


COMPULOCKS

1




USING THE ALCOHOL WIPE PROVIDED,
CLEAN A 130mm SQUARE AREA CENTERED
ON THE BACK OF THE TABLET
AND ALLOW IT TO DRY

2



INSTALL CASE ON TABLET.
EDGE CASE SOLD SEPARATELY


3



CONNECT RIGHT ANGLE USB-C CABLE
AS SHOWN, ENSURING YOUR TABLET
AND CONNECTOR ARE IN LANDSCAPE ORIENTATION

4


REMOVE COVERS TO EXPOSE
ADHESIVE ON ALL 4 PADS



NOTE:
TABLET AND CONNECTOR SHOULD BE AT
ROOM TEMPERATURE FOR BEST RESULTS

5

CENTER CONNECTOR AND ADHERE
TO TABLET WITH MILD PRESSURE




FOR BEST PERFORMANCE ALLOW
CONNECTOR TO BOND TO TABLET FOR 12 HOURS

IN THE BOX



Alcohol Wipes



PowerMove Connector