

1




REMOVE MOUNT FROM DEVICE BY REMOVING
THE M4 PIN TORX SCREWS USING THE PROVIDED
T-15 SCREWDRIVER. THIS EXPOSES THE FOUR (4) ADHESIVE PADS.

2



PLACE TABLET OR LAPTOP ON A FLAT PROTECTIVE SURFACE WITH THE 4 ADHESIVE PADS FACING UP. WHILE SECURELY HOLDING THE DEVICE, PLACE THE TOOL ONTO THE ADHESIVE PAD AS SHOWN AND ROTATE WITH STEADY FORCE ALLOWING THE ADHESIVE TO BREAK FREE.

3



IF ANY ADHESIVE REMAINS ON THE DEVICE IT CAN BE REMOVED USING AN ADHESIVE REMOVAL SOLUTION COMPATIBLE WITH THE DEVICE. DO NOT USE SOLVENT.